



#### **ABOUT THE PROPERTY**

Market	Midtown		
Year Built/Year Retrofitted	1953/2000 (renovated)		
Class	А		
Typical Floor Plate	13,500 SF		
Net Rent	Contact listing agent for details		
2025 Additional Rent Estimates (*includes in suite janitorial & utilities)	Operating Costs \$19.65/SF Realty Tax \$5.32/SF TOTAL \$24.97/SF		

#### **PARKING**

Number of Parking Spaces	104	
Ratio	1/1,500 SF leased	


#### **TECHNICAL SPECIFICATIONS**

Elevators	2 passenger, 1 dual purpose passenger & freight	
HVAC	Heat pump; 4 zones/floor	
HVAC After Hours Cost	Available upon request	
Sprinklers	•	
Security	Onsite, manned security	
Barrier Free	<b>♥</b> Wheelchair accessible	
Telco Providers	Bell, Rogers, AT&T & Telus	
Environmental Certification	BOMA Best Silver	

#### **LEASING OPPORTUNITIES**

SUITE	SF	AVAILABILITY	NOTES
201	1,559	LEASED	
305	3,061	IMMEDIATE	
500	3,208	IMMEDIATE	
600	2,446	IMMEDIATE	
601	2,441	LEASED	
700	7,668	IMMEDIATE	
800	6,134	IMMEDIATE	CONTIGUOUS UP TO
806	878	SEP. 1/2025	7,012 SF

### **STACKING PLAN**



South facing exterior shown.




### RECENT BUILDING UPDATES

PROJECT	PROJECT DETAILS	TENANT BENEFITS
Main Lobby Entrance Updates	Updated façade, new revolving and glass doors, new access card reader, new building signage	Improved tenant and visitor experience
Main Entrance Podium Repairs and Waterproofing	Replacement of waterproofing system and new pavers, future new podium sign	Improved tenant and visitor experience
Washroom Refresh Program	Updated finishes and fixtures in common washrooms including touchless door openers and washroom fixtures	Improved tenant and visitor experience
Security Access Card System Update	Replacement of building card access system	Improved security services platform
Booster Pump Replacement	Replacement of building mechanical system equipment	Improved energy and operating cost management
Heat Pump Replacement Program	Replacement of building heat pumps, components of the HVAC system	Improved tenant comfort, improved energy and operating cost management
Building Automation System (BAS) Replacement	Replacement of base building HVAC equipment controls system to advanced platform	Improved equipment controls to enable greater tenant comfort levels, energy efficiency
Parking Garage Exhaust Fans	Replaced all garage exhaust fans	Improved equipment controls for enhanced air quality in parking garage
Heating System	Replaced two heating boilers with high efficiency boilers	Improved equipment controls to enable greater tenant comfort levels, energy efficiency




#### **ABOUT THE SUITE**

▶ 3,061 SF



KEY PLAN





— Demising wall



#### **ABOUT THE SUITE**

▶ 3,208 SF







KEY PLAN



#### **ABOUT THE SUITE**

▶ 2,446 SF









#### **ABOUT THE SUITE**

▶ 7,668 SF



KEY PLAN





— Demising wall



#### **ABOUT THE SUITE**

▶ 6,134 SF













#### **ABOUT THE SUITE**

▶ 878 SF





— Demising wall





adgarcanada.com

### FOR MORE INFORMATION PLEASE CONTACT:

TONY HAMILTON\* Vice President

416.804.2235

✓ tony.hamilton@cushwake.com

### cushwake.com

Cushman & Wakefield ULC, Brokerage. No warranty or representation, expressed or implied, is made as to the accuracy of the information contained herein, and same is submitted subject to errors, omissions, change of price, rental or other conditions, withdrawal without notice, and to any specific listing condition, imposed by our principals. \* Sales Representative.



40 EGLINTON AVENUE EAST