



PROPERTY INFORMATION

- VACANT BUILDING FOR SALE/LEASE
- ABILITY TO ADD 80,000 SF OUTDOOR STORAGE OR EXPAND THE BUILDING
- FULLY CLIMATE CONTROLLED WAREHOUSE
- HEAVY POWER

Address	4500 Valley Industrial Blvd S Shakopee, MN		
Building Size	5,000 SF Office 4,730 SF Mezzanine 50,965 SF Warehouse 60,695 SF Total		
Outdoor Storage	Approximately 2 Acres		
Lease Rates	Negotiable		
Sale Price	Negotiable		
Loading	3 Docks 1 Drive-in		
Clear Height	18'		
Roof	1988		
Power	2,000 amps / 480 volt / 3-phase 1,200 amps / 208 volt / 3-phase		
Year Built	1988		
Column Spacing	25' x 55'		
2025 Property Taxes	\$150,220 (\$2.47 PSF)		

KRIS SMELTZER

Executive Managing Director +1 952 837 8575 kris.smeltzer@cushwake.com

CHARLES MERWIN

Senior Director +1 612 347 9346 charlie.merwin@cushwake.com

HUDSON BROTHEN

Executive Director +1 952 893 8261 hudson.brothen@cushwake.com

CLINT MOE

Senior Associate +1 952 221 1380 clint.moe@cushwake.com



HVAC AND ROOF DETAILS



EQUIPMENT DESCRIPTION	MODEL NUMBER	SIZE	MANUFACTURE DATE
BRYANT ROOFTOP UNITS (6 TOTAL)	581JE24D310 OR SIMILAR	10 TONS	2013
CARRIER ROOFTOP UNITS (2 TOTAL)	48KCEA05 OR SIMILAR	5 TONS	1997
CARRIER ROOFTOP UNIT (1 TOTAL)	48KCEA05	5 TONS	2018
CARRIER ROOFTOP UNIT (1 TOTAL)	48HCED11	11 TONS	2018
DAIKIN DUCTLESS MINI-SPLITS (2 TOTAL)	NOT VISIBLE	NOT VISIBLE	NOT VISIBLE

ROOFING MATERIALS, CONDITION, AND ANALYSIS 4.4 ROOF

4.4.1 ROOFING MATERIALS

ROOF COVERINGS CONSISTED OF BUILT-UP ROOFING WITH ASPHALT FLOOD COAT EMBEDDED AGGREGATE SURFACE OVER LOW-SLOPE ROOF CONSTRUCTION.

EXTERIOR WALLS EXTENDED ABOVE THE ROOF PLANE AS PARAPETS AND WERE CAPPED WITH COPING. ROOF MATERIALS COVERED THE INBOARD SIDES OF THE PARAPETS. MATERIALS TERMINATED UNDER THE METAL COPING. FLASHING MATERIALS APPEARED TO BE SIMILAR TO THE ROOFING MEMBRANE AND METAL.

CONVENTIONAL TRANSLUCENT ACRYLIC SKYLIGHTS WERE PROVIDED. THE SKYLIGHTS WERE FACTORY FLASHED.

SURVEY CONDITION AND ANALYSIS

THE ROOFING SYSTEMS APPEARED TO BE IN FAIR OVERALL CONDITION. THE ROOF WAS REPORTEDLY ORIGINAL AND INSTALLED IN 1988. BASED ON OUR OBSERVATIONS, THE REPORTED AGE APPEARED TO BE REASONABLE. BASED ON EUL, REPLACEMENT OF THE BUR ROOF SYSTEM IS ANTICIPATED EARLY IN THE EVALUATION PERIOD. AN OPINION OF COST FOR THIS WORK IS INCLUDED IN TABLE 2.

PARAPETS APPEARED TO BE IN GOOD OVERALL CONDITION. ROUTINE MAINTENANCE IS ANTICIPATED THROUGHOUT THE EVALUATION PERIOD.

SKYLIGHTS APPEARED TO BE IN GOOD CONDITION. NO EVIDENCE OF WATER INTRUSION WAS NOTED. ROUTINE MAINTENANCE IS EXPECTED THROUGHOUT THE EVALUATION PERIOD.

PROPERTY CONDITION REPORT

PROJECT NO: 22-3683641


CUSHMAN & WAKEFIELD

PROPERTY PHOTOS


















CUSHMAN & WAKEFIELD

AMENITY/DRIVE TIMES





KRIS SMELTZER

Executive Managing Director +1 952 837 8575 kris.smeltzer@cushwake.com

HUDSON BROTHEN

Executive Director +1 952 893 8261 hudson.brothen@cushwake.com

CHARLES MERWIN

Senior Director +1 612 347 9346 charlie.merwin@cushwake.com

CLINT MOE

Senior Associate +1 952 221 1380 clint.moe@cushwake.com 3500 American Blvd W, Suite 200 Minneapolis, MN 55431 952 831 1000 industrialmn.com

©2025 Cushman & Wakefield. All rights reserved. The information contained in this communication is strictly confidential. This information has been obtained from sources believed to be reliable but has not been verified. NO WARRANTY OR REPRESENTATION, EXPRESS OR IMPLIED, IS MADE AS TO THE CONDITION OF THE PROPERTY (OR PROPERTIES) REFERENCED HEREIN OR AS TO THE ACCURACY OR COMPLETENESS OF THE INFORMATION CONTAINED HEREIN, AND SAME IS SUBMITTED SUBJECT TO ERRORS, OMISSIONS, CHANGE OF PRICE, RENTAL OR OTHER CONDITIONS, WITHDRAWAL WITHOUT NOTICE, AND TO ANY SPECIAL LISTING CONDITIONS IMPOSED BY THE PROPERTY OWNER(S). ANY PROJECTIONS, OPINIONS OR ESTIMATES ARE SUBJECT TO UNCERTAINTY AND DO NOT SIGNIFY CURRENT OR FUTURE PROPERTY PERFORMANCE.

